

Glazier (FG-2) 865.381.010

The following schedule of work experience is intended as a guide. It need not be followed in any particular sequence, and it is understood that some slight adjustments may be necessary in the hours allotted for different work experience. In all cases, the apprentice is to receive sufficient experience to make him fully competent in all work processes which are a part of the trade. The apprentice will be fully instructed in safety and OSHA requirements. PLEASE NOTE: Connecticut Occupational Licensing Regulations require a minimum number of O.J.T. years (*calendar time*) as expressed below.

- A. Tools and equipment, shop training, scaffold, safety measures, first aid, reading of specifications, and field blueprint reading (500 HOURS)
- B. Glazing, wood and metal sash, tube doors, partitions, and all other types of openings with, but not limited to, putty, moldings, rubber, plastic, gasket settings, sealants, and mastics (300 HOURS)
- C. Setting all types of store front, curtainwall, windowall, revolving doors, pressurewall, ribbon window systems, structural glazing, and suspended glazing installations (1,200 HOURS)
- D. Setting all types of plate glass, prism glass, beveled glass, protective glass, glassweld, panels, window glass, mirrors of all types, wire glass, ribbed glass, heat absorbing glass, ground glass, colored glass, figured glass, vitrolite, carrata glass, and all other types of opaque glass, glass chalkboard, tempered glass and all types of insulating glass units which could be used as a solar energy system, window panels, and similar types of insulated glass, all plastic or other similar materials when used in place of glass, to be set or glazed with putty, molding, rubber, gasket settings, sealants, and all types of mastics in wood, iron, aluminum or sheet metal sash, skylight, doors, frames, stone, wall case, showcases, bookcases, sideboards, partitions, and fixtures, etc., temporary or permanent, on or for buildings in the course of construction or repair or replacement (2,000 HOURS)
- E. Doors, frames, and tube work, prefabricated units, fabricated units, fabrication in shop or on the job site, setting shower doors tub enclosure (500 HOURS)
- F. Setting all types of multiple glazed units (300 HOURS)
- G. Setting all types of automatic doors, hinges, etc. (500 HOURS)

- H. Handling and use of all products associated with the glass industry (100 HOURS)
- I. Replacement of any and all of the above named materials (200 HOURS)
- J. All types of equipment needed or used to install or replace the above named materials (200 HOURS)
- K. All types of miscellaneous glazing (200 HOURS)

TOTAL = 6000 HOURS

- L. RELATED INSTRUCTION = 432 HOURS
Minimum O.J.T. Years = 3

WAGE SCHEDULE

0 - 1000	Hours	_____
1001 - 2000	Hours	_____
2001 - 3000	Hours	_____
3001 - 4000	Hours	_____
4001 - 5000	Hours	_____
5001 - 6000	Hours	_____
Journeyman	Rate	_____